



REPUBLIC OF THE PHILIPPINES
NATIONAL DISASTER RISK REDUCTION AND MANAGEMENT COUNCIL

National Disaster Risk Reduction and Management Center, Camp Aguinaldo, Quezon City, Philippines

National Disaster Risk Reduction and Management Council

INCIDENTS MONITORED

Progress Report no. 1 on the Effects of Localized Thunderstorms, ITCZ, and LPA in the Province of Sultan Kudarat (Region XII)

DATE OF INCIDENT	June 25, 2024
TIME OF INCIDENT	10:00 am
DATE ISSUED	July 04, 2024
TIME ISSUED	01:00 pm
OVERVIEW	<p>On 25-26 June 2024-02 July 2024, continuous heavy rainfalls were experienced in the Province of Sultan Kudarat brought by localized thunderstorms, ITCZ, and LPA. This resulted in flashflood incidents in Esperanza and Lambayong and the presence of tension cracks in Bagumbayan.</p> <p>Chronology:</p> <p>On June 25, 2024, 10:00 AM, the presence of tension cracks in Barangay Masiag, Bagumbayan, Sultan Kudarat due to continuous heavy rainfall brought about by localized Thunderstorms was reported. The said tension cracks caused damages to several houses and roads (graveled road) in the affected area.</p> <p>On June 26, 2024, 5:30 PM, a flashflood incident that happened in Esperanza, Sultan Kudarat when creeks overflowed due to continuous heavy rainfall brought about by the ITZC/LPA was reported. The said incident affected families in the said area.</p> <p>On June 26, 2024, 11:30 PM, a flashflood incident that happened in Lambayong, Sultan Kudarat when the Allah River overflowed due to continuous heavy rainfall brought about by the ITZC/LPA was reported. The said incident affected families in the said area.</p> <p>On 30 June 2024, around 09:00 PM, a landslide incident (rain-induced) due to heavy rainfall brought about by ITCZ occurred in Brgy. Kadi and Brgy. Bugso in Sen. Ninoy Aquino, Sultan Kudarat. The said incident affected families, houses and roads in the said Barangays.</p> <p>On 02 July 2024, at around 5:00 AM, a flooding incident occurred in, Barangay Lutayan Proper, Municipality of Lutayan, Sultan Kudarat due to continuous moderate to heavy rainfall brought about by ITCZ. The incident affected families in the said barangay.</p> <p>On 02 June 2024, around 11:00 PM, a landslide incident (rain-induced) due to heavy rainfall brought about by ITCZ occurred in Brgy. Chua in Bagumbayan, Sultan Kudarat. The said incident affected families, houses and roads in the said Barangays.</p>

RELATED INCIDENTS

The following incidents were reported in some areas of SULTAN KUDARAT.

PROVINCE	Tension Cracks	Flooded Areas			Landslide (Rain-Induced)
		Flooded	Subsided	Receding	
Total	1	0	3	0	2
SULTAN KUDARAT	1	0	3	0	2

AFFECTED POPULATION

A total of 1,149 families or 3,980 persons were affected. Of which, 22 families or 0 persons were served inside 2 ECs and 0 families or 0 persons were served outside ECs:

Affected Provinces	AFFECTED			INSIDE ECs			OUTSIDE ECs	
	Brgy	Families	Persons	No. of ECs	Families	Persons	Families	Persons
TOTAL	11	1,149	3,980	2	22	0	0	0
SULTAN KUDARAT	11	1,149	3,980	2	22	0	0	0

Esperanza and Lambayong: No evacuation was reported on flashflood incidents.
Bagumbayan and Sen Ninoy Aquino: Number of families inside Brgy Gym is still for validation.

ROADS AND BRIDGES

A total of 0 road sections and 1 bridges were affected. Below is the current status of affected road sections and bridges:

	NOT PASSABLE		PASSABLE (previously reported as not passable and/or one lane passable)	
	ROADS	BRIDGES	ROADS	BRIDGES
GRAND TOTAL	0	0	0	1
SULTAN KUDARAT	0	0	0	1

DAMAGED HOUSES

A total of 29 damaged houses are reported in SULTAN KUDARAT.

REGION	PARTIALLY	TOTALLY	TOTAL	AMOUNT (PHP)
GRAND TOTAL	22	7	29	0
SULTAN KUDARAT	22	7	29	0

On going validation of damage houses in other sitios.

Related Incidents

REGION PROVINCE CITY/ MUNICIPALITY BARANGAY		TYPE OF INCIDENT	DATE OF OCCURENCE	TIME OF OCCURENCE	DESCRIPTION	ACTIONS TAKEN	REMARKS	STATUS (for flooded areas)
GRAND TOTAL	6							
REGION 12	6							
SULTAN KUDARAT	6							
Bagumbayan	2							
		Tension Cracks	25 June 2024	10:00 am	tension cracks affected roads and houses			
		Landslide (Rain-Induced)	02 July 2024	11:00 pm	affected roads			
Esperanza	1							
		Flooded Areas	26 June 2024	05:30 pm	affected families and houses			Subsided
Lambayong (Mariano Marcos)	1							
		Flooded Areas	26 June 2024	11:30 pm	affected families and houses			Subsided
Senator Ninoy Aquino	1							
		Landslide (Rain-Induced)	23 June 2024	09:00 pm	affected roads and houses			
Lutayan	1							
		Flooded Areas	02 July 2024	05:00 am	affected families and houses			Subsided

Affected Population

REGION PROVINCE CITY/ MUNICIPALITY BARANGAY		NO. OF AFFECTED			No. of ECs		Inside Evacuation Centers				Outside Evacuation Centers				TOTAL SERVED (CURRENT)			
															(Inside + Outside)			
		Brgys.	Families	Persons			Families		Persons		Families		Persons		Families		Persons	
					CUM	NOW	CUM	NOW	CUM	NOW	CUM	NOW	CUM	NOW	CUM	NOW		
GRAND TOTAL	5	11	1,149	3,980	2	2	22	22	0	0	0	0	0	0	22	22	0	0
REGION 12	5	11	1,149	3,980	2	2	22	22	0	0	0	0	0	0	22	22	0	0
SULTAN KUDARAT	5	11	1,149	3,980	2	2	22	22	0	0	0	0	0	0	22	22	0	0
Bagumbayan	1	1	21	94	1	1	13	13	0	0	0	0	0	0	13	13	0	0
		1	21	94	1	1	13	13	0	0	0	0	0	0	13	13	0	0
Esperanza	1	6	71	363	0	0	0	0	0	0	0	0	0	0	0	0	0	0
		6	71	363	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Lambayong (Mariano Marcos)	1	1	441	1,399	0	0	0	0	0	0	0	0	0	0	0	0	0	0

REGION PROVINCE CITY/ MUNICIPALITY BARANGAY		NO. OF AFFECTED			No. of ECs		Inside Evacuation Centers				Outside Evacuation Centers				TOTAL SERVED (CURRENT)			
															(Inside + Outside)			
		Brgys.	Families	Persons			Families		Persons		Families		Persons		Families		Persons	
					CUM	NOW	CUM	NOW	CUM	NOW	CUM	NOW	CUM	NOW	CUM	NOW		
		1	441	1,399	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Senator Ninoy Aquino	1	2	9	0	1	1	9	9	0	0	0	0	0	0	9	9	0	0
		2	9	0	1	1	9	9	0	0	0	0	0	0	9	9	0	0
Lutayan	1	1	607	2,124	0	0	0	0	0	0	0	0	0	0	0	0	0	0
		1	607	2,124	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Esperanza and Lambayong: No evacuation was reported on flashflood incidents.
 Bagumbayan and Sen Ninoy Aquino: Number of families inside Brgy Gym is still for validation.

Roads and Bridges

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	CLASSIFICATION	ROAD SECTION/BRIDGE	STATUS	DATE REPORTED (passable)	TIME REPORTED (passable)	DATE REPORTED (not passable)	TIME REPORTED (not passable)	REMARKS
GRAND TOTAL	1									
REGION 12	1									
SULTAN KUDARAT	1									
Bagumbayan	1									
		Bridge	National (tertiary)	S00743MN - Isulan Jct-Ninoy Aquino Rd K1816+0250 to K1816+0280 Brgy. Chua, BAGUMBAYAN, Sultan Kudarat	OLP - ONE LANE PASSABLE	03 July 2024	10:00 pm	03 July 2024		-Fallen Trees, Soil Slope Collapse. -Continuous monitoring of affected infrastructure Clearing operations is ongoing Installed warning signs.

Damaged Houses

REGION PROVINCE CITY/ MUNICIPALITY BARANGAY	NO. OF DAMAGED HOUSES			AMOUNT (PHP)	REMARKS
	TOTALLY	PARTIALLY	GRAND TOTAL		
GRAND TOTAL	7	22	29	0	
REGION 12	7	22	29	0	
SULTAN KUDARAT	7	22	29	0	
Bagumbayan	7	13	20	0	
1	7	13	20	0	

REGION PROVINCE CITY/ MUNICIPALITY BARANGAY	NO. OF DAMAGED HOUSES			AMOUNT (PHP)	REMARKS
	TOTALLY	PARTIALLY	GRAND TOTAL		
Senator Ninoy Aquino	0	9	9	0	
2	0	9	9	0	

On going validation of damage houses in other sitios.

**Progress Report no. 1 on the Effects of Localized Thunderstorms, ITCZ, and LPA in the
Province of Sultan Kudarat (Region XII)
ACTIONS TAKEN**

Region 12

PGU Sultan Kudarat

- Close coordination with the affected LGUs.
- Monitored the weather status through the Local DRRM Operation Centers and LDRRMOs GC.

LGU Senator Ninoy Aquino

- MDRRMC SNA conducted damage assessment in the affected areas.
- LGU SNA transported affected families to a safe location (within the same barangay), where they are currently staying with their relatives.
- MDRRMO SNA closely coordinated with affected Barangays.
- MDRRMO SNA conducted information dissemination within area of responsibility.

LGU Lutayan

- MDRRM OPCEN provided advisory to all BDRRMCs in the Municipality that Easterlies/ Wind Convergence will affect the municipality and may bring moderate to heavy rains.
- MDRRM OPCEN advised all BDRRMCs to monitor installed water level gauges and take necessary precautionary measures.
- MEO conducted declogging and clearing operations of affected culvert box situated in the mentioned barangay.
- DRRMC was advised to open the Barangay Gym for possible evacuation of the affected residents.

LGU Bagumbayan

- MDRRMO Response, Monitoring and Damage Assessment Team conducted inspection of damages in the affected areas.
- Deployed RDANA Team to affected areas.
- Continuous monitoring of AOR concerned by the MDRRMO with the Masiag and Chua Barangay Officials and BDRRM Committee.

LGU Esperanza

- MDRRMO conducted assessment and validation in the affected areas.
- Continuous monitoring of water levels in waterways in the affected areas.

LGU Lambayong

- MDRRRMO Lambayong conducted assessment and validation of areas affected by flashflood.
- Deployed RDANA Team to the affected areas

DPWH XII

- Deployed personnel and equipment to clear debris in landslide affected road network in Esperanza and Bagumbayan Sultan Kudarat.

DSWD XII

DSWD FO XII coordinated with MSWDO Lambayong for validation and gathering of initial disaster data.

OCD XII

Continuous monitoring and coordination with concerned LGUs.